



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

S0230078
Internal

0001

Inspection Report
Minerals Regulatory Program
Date: April 02, 2009

Reviewed: LK

Mine Name: Green Mile Mine	Permit Number: S/023/0078
Operator Name: Amy Sabey	Inspection Date: 04/01/2009
Inspector(s): Wayne Western, Brent Gregory	Time: 2:40 pm – 2:55 pm
Other Participants: Jerry Mansfield	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	X	X	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: Annual Inspection

Inspection Summary:

The inspection team looked at the site and agreed with the findings that the site have been properly backfilled and graded. The team looked at the vegetation and notice that the amount of cover was not the same as the surrounding areas.

The Division took photographs of the site to document the amount of vegetation.

Conclusions and Recommendations:

The team found that the site had been adequately backfilled and graded. The Division recommends that the Permittee pursue total bond release. The Permittee's options are to reseed the site and apply for bond release when the vegetation ground cover is 70% of the surrounding area or apply for bond release under R647-3-109-13.12. The Division usually considers that practical limits to mean that the site was properly seeded twice. In order to apply for bond release under R647-3-109-13.12 the Division would need to have the Permittee document with seed tags and photographs they made at least two attempts to seed the area.

Inspector's Signature Wayne Western

(WHW):pb

cc: Amy Sabey
Jerry Mansfield BLM

O:\M023-Juab\S0230078-GreenMile\inspections\INSP-04012009.doc

0001